

Vitruvian Park
Project 10.025.01.F

KBA EnviroScience, Ltd.

Prepared by: J. Kemmey
February 13, 2015

Figure 1. Aerial Photograph and Mitigation Monitoring Station Locations for Vitruvian Park Development, Addison, Dallas County, Texas



Photo 1. Recent view, facing southwest, of existing riparian buffer in southern portion of project site.



Photo 2. Recent view, facing northeast, of existing riparian buffer in southern portion of project site.



Photo 3. View, facing northeast, of previously existing riparian zone in southern portion of project site.



Photo 4. View, facing south, of previously existing riparian area in southern portion of the project site.



Photo 5. Recent view, facing west, of existing riparian zone in the northern portion of the project site.



Photo 6. Recent view, facing northwest, of existing riparian zone in northern portion of the project site.




Photo 7. View, facing northeast of previously existing riparian area in northern portion of project site.



Photo 8. View, facing southwest, of previously existing riparian area in northern portion of project site.